


DESIG		DRAWN BY	DART AEROSPACE HAWKESBURY, ONTARIO, CANA	
CHEC	(ED	APPROVED	DRAWING NO.	REV. A
	4	THE THE	DSI 9333	SHEET 1 OF 1
DATE	, ,		TITLE	SCALE
06.05.11			STEP MODIFICATION	NTS
Α		06.05.11	NEW ISSUE	

## DART SERVICE INSTRUCTION

TO AMEND DRAWING D350-591 REV. F REF. CANADIAN STC: SH92-6 FAA STC: SH967NE

ADD THE FOLLOWING NOTE IN REGARDS TO TORQUING THE AN5-36A BOLTS AT AFT SUPPORT ON THE D350-591-311/-312 STEPS AS SHOWN ON SECTION P-P:

A MINIMUM TORQUE IS NOT REQUIRED ON THE AN5-36A BOLTS. ENSURE THE HARDWARE IS PROPERLY INSTALLED WITH A MINIMUM OF 1.5 THREADS IN SAFETY.



A MINIMUM TORQUE IS NOT REQUIRED ON THE AN5-36A BOLTS. ENSURE THE HARDWARE IS PROPERLY INSTALLED WITH A MINIMUM OF 1.5 THREADS IN SAFETY.

> CANADA DEPARTMENT OF TRANSPORT AIRCRAFT CERTIFICATION BRANCH DAO # 01-O-01

APPROVED BY: D. SHEPHERS (DE # 02)

DATE: 06.05.11 CERT. NO.: SH92-6 ISSUE NO.: 10